





3 10 0023



January 10, 1991

United States Environmental Protection Agency  
Region IV  
345 Courtland Street, N.E.  
Atlanta, Georgia 30365



Re: Submittal of Figure 3.6 of the Draft RI Report  
Medley Farm Site  
Gaffney, South Carolina

Dear Jon:

Please find enclosed two copies of Figure 3.6 that was inadvertently left out of the Draft Medley Farm Site RI Reports submitted to you in November, 1990. I apologize for any inconveniences that this may have caused during your review process. Also enclosed is a copy of a letter to Mr. Wade Knight (USEPA-ESD) that accompanied the data packages that had been requested.

If you have any questions or need additional information, please feel free to contact me at anytime at (803) 234-3046.

Sincerely,

A handwritten signature in cursive script, reading 'Richard L. Burdine'.

Richard L. Burdine, P.G.  
Project Geologist


cc: Mr. James Chamness, SIRRINE  
File



3 10 0024

January 10, 1991

United States Environmental Protection Agency  
Laboratory Evaluation and Quality Assurance Section  
Environmental Services Division  
Athens, Georgia 30613



Attn: Mr. Wade Knight

Re CLP Data Packages for Split Samples  
Medley Farm Site  
Gaffney, South Carolina

Dear Mr. Knight:


Analytical data packages for two ground-water samples (SW109-3 and BW108-3) collected during the Phase II Remedial Investigation at the Medley Farm site, that were split with the EPA-Region IV representative, are enclosed for your review. Also enclosed, please find the analytical data packages for the EPA spike samples that were sent to the contract laboratory for analysis.

If you have any questions or need further assistance, please feel free to contact me at (803) 234-3046.

Sincerely,

Richard L. Burdine, P.G.  
Project Geologist

cc: Mr. Jon Bornholm, USEPA-Region IV  
Mr. James Chamness, SIRRINE  
File




Draft

FIGURE 3.6  
MONITORING WELL  
LOCATIONS AND  
SITE LINEMENTS

Medley Farm Site  
Gaffney, South Carolina  
Remedial Investigation/  
Feasibility Study

**SIRRIE**  
ENVIRONMENTAL  
CONSULTANTS  
Greenville, South Carolina



3 10 0020

HORIZONTAL CONTROL POINT  
VERTICAL CONTROL POINT  
WATER CONTOUR  
INTERMEDIATE CONTOUR  
DEPRESSION CONTOUR  
SPOT ELEVATION  
POLE  
WATER  
IMPROVED ROAD  
UNIMPROVED ROAD  
BUILDING  
LOCATED UNDEVELOPED  
FENCE  
FILL  
TREES  
BRUSH

Success Location of Ground  
Water Monitoring Well at  
Intersection

NOTES:  
Ground Water Monitoring wells were  
installed from May to August 1999 by  
Environmental Drilling and Services  
Inc. of Anderson, S.C. and August to  
October 1999 by Marine Testing and  
Engineering of Raleigh, NC.  
Surveying was completed by Sirmine  
Environmental Consultants at Charleston, SC.

**Draft**

FIGURE 3.6  
MONITORING WELL  
LOCATIONS AND  
SITE LINEAMENTS

Medley Farm Site  
Gaffney, South Carolina  
Remedial Investigation/  
Feasibility Study

**SIRRIINE**  
ENVIRONMENTAL  
CONSULTANTS  
Greenville, South Carolina